### CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BCF OIL REFINING CONTRACT NO. 68-S2-99-07

ORDER NO.: 19

SITE/SPILL NO.: PU

EPA REGION: II

DATE(s): 2/9/01
SHIFT:0700 - 1530
OSC: Thomas P.Budroe

CONTRACTOR: WRS Infras. & Env., Inc. WORK ORDER #57
MONITORS: None RM: Bob Moody

### DESCRIPTION OF WORK TO BE PERFORMED

1) Provide form 1900-55s to the OSC for approval.

- 2) Continue providing 24 hour security for the Site. One person acting as the guard will be on-site at all times. Each guard will work an eight hour shift. Each guard will key-in at the appropriate time and location at each key-box. The guard will periodically inspect the site for any releases, spills, leaks, fires, etc.
- 3) Conduct daily safety briefing.
- 4) Continue heating tanks 11,12 and 17 with steam as appropriate.
- 5) Load tank trucks with oil from the appropriate tanks and from the appropriate drums staged on Site and complete all necessary shipping paperwork (manifest). Construct a loading/containment area prior to loading this material.
- 6) Complete a Daily Work Summary outlining daily accomplishments.
- 7) Procure an oil/water separator and coalescer for pre-treating the aqueous waste.
- 8) Procure a qualified subcontractor to remove and dispose of the asbestos on the pipe in the back room of the boiler house.
- 9) Remove all surface pipes, pumps and other appurtenances overlaying tanks 15 and 16.
- 10) Load contaminated water from the appropriate tanks for disposal.
- 11) Bring the appropriate tank cutting equipment to Site to cut the tops off the USTs.
- 12) Begin pretreating and disposing of the aqueous waste in underground tanks 15 and 16.
- 13) Remove all other liquid wastes from tanks 15 and 16.
- 14) Demobe the excavator from the Site.
- 15) Obtain waste delivery confirmation from Safety Kleen and provide same to EPA.
- 16) Conduct other tasks as necessary in preparation of loading the waste materials on Site into trucks for disposal.

## NUMBER OF PERSONNEL AUTHORIZED

1-RESPONSE MANAGER 0-FOREMAN 5-CLEANUP TECHNICIAN(S) 1-PCT 0-CHEMIST 1-EQUIPMENT OPERATOR 0-LAB TECH 0-T&D Coordinator

### EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED

ITEM	OUANT.	ITEM	OUANT,
PICK UP TRUCK (1/4 TON)	4	FAX	1
OVERPACKS	0'	RADIO HAND HELD	3
EXCAVATOR	0	LAPTOP COMPUTER	2
PORTABLE BOILER	1	COMPUTER PRINTER	2
PHOTOCOPIER	1	CELLULAR TELEPHONE	1

# CERCLA REMOVAL ACTION DAILY WORK ORDER

SITE NAME: BCF OIL REFINING	CONTRACT NO. 68-S2-99-07			
ORDER NO.: 19	DATE(s): 2/9/01			
SITE/SPILL NO.: PU	SHIFT:0700 - 1530			
EPA REGION: II	OSC: Thomas P.Budroe			
CONTRACTOR: WRS Infras.& Env., Inc.				
•	RM: Bob Moody			
1,010	idi. Box noody			
I CERTIFY THAT THE ABOVE WORK IS ORDERE	ה אאה אווייט סדיקפה פע ייטפ			
CONTRACTOR IN THE PERFORMANCE OF THE ABOVE CITED DELIVERY ORDER				
CONTRACTOR IN THE PERFORMANCE OF THE AD	OVE CITED DELIVER! ORDER			
<b></b>				
SIGNATURE OF ON-SCENE COORDINATOR	rum V. Hustral			
I ACKNOWLEDGE RECEIPT OF THIS WORK ORDE	R.			
SIGNATURE OF CONTRACTOR'S REPRESENTATIVE				
	1 ( ) (			
	10,			
DESCRIPTION OF SUPPLIES REQUIRED				
•	•			
	**************************************			
•				
Amendments:				
	•			
SIGNATURE OF ON-SCENE COORDINATOR				
<u></u>				
	_			
SIGNATURE OF CONTRACTOR'S REPRESENTATIVE	<u> </u>			